

# How to check quality of aluminium doors and windows

**Thickness of material** – *it should be at least 1.1mm minimum or simple check that it should not be pressed by hand pressure*

**Joints**- *Joints form very significant part in frames and shutters if the joints are very thin and linear then only the window will look attractive. The sections forming the joints should be cut in such a way that there is almost no gap in between.*

**Lock holes**- It is generally drilled or cut manually and hence always of worry to the owner. If these are made on automatic machines then they look very orderly and attractive giving fine-looking finish to windows.

**Holes** - *The shutter section holes must be closed to impart the tidy look to windows but regrettably it seems to be forgotten by many.*

**Screws**- Star head screws give much superior effect even though it's costly.

**Coating** – *if coating is of standard or branded make powder then peeling and getting dull over period of time will never occur.*

## RollwinIndia

---

[www.rollwinindia.com](http://www.rollwinindia.com)